

NZAA – VHHH ABC901 17APR

NOTAM Summary



How this works

This NOTAM Summary is designed as an **add-on** to the routine NOTAM package, to help you to **identify critical NOTAMs**.

All original NOTAMs remain in your normal brieing pack, and remain the primary source for NOTAM information.

Contents

Some note like this to flight crew will be helpful to make sense of this summary package.

- A Departure Airport
- **B** Destination Airport
- Alternates (Dep, Dest, Enroute)
- **Enroute** (FIR Notams)

TAG SUMMARY ID ORIGINAL NOTAM

AIRPORT

Closed Restriction Airport closed, staff shortage Do not use as alternate

A0133/22

APT CLSD DUE TO STAFF SHORTAGE DAILY 0600-1100Z

APT NOT AVBL AS ALTERNATE 2200-0400Z A0233/22

APPROACH

Not avail Degraded Arrival

ILS Runway 06 U/S Outer marker on test **BUNON 3D STAR restriction** A0233/22

ILS/DME RWY 06 U/S DUE TO MAINT WEEKDAYS 0800-1400Z PILOTS TO EXER CTN AS SI

ILS OM RWY 24 ON TEST DO NOT USE A0233/22

A0233/22

BUNON3D CAT A/B/C/D STAR RWY24 NOT AVBL TO CAT D AIRCRAFT

RUNWAY

Closed Length Note

RWY 06/24 closed **RWY 06 TORA reduced** Delays for RWY 06/24

A0178/23

RWY 06/24 CLOSED FOR LANDING AND TAKE OFF EXCEPT FOR SAR REF AIP SUP 010/202

TORA RWY 06/24 RED TO 2243M THR DISPLACED A0001/23

REINSTATING RWY 06/24 TO FULL LENGTH - EXPECT DELAYS OF 20 MINUTES. REF AIP A0128/23

TAXIWAY

Closed Closed Taxiway D1 closed Taxiway A closed

A012/23

TWY D1 CLOSED REF AIP SUPPLEMENT 021/2022

A013/23

TWY A CLOSED ACFT SHOULD EXPECT TO BACKTRACK TO VACATE 06/24 VIA TWY D1

ATC

Hours Radio Tower closed at night Approach frequency problem

A021/22 A029/23 ATC SER NOT AVBL DURING NIGHT HOURS (2300-0500 UTC) DUE TO STAFF SHORTAGE AI

Non-critical Notams

eg. Birds, Fireworks. We just give a plain english summary of

are sent to the DARK -

each one here.

APP CNTL FREQ 121.4 ON BACKUP ALTN FREQ 119.7 IF ANY COMMS ISSUES

Critical Notams are decided in the MATRIX. Sorted by tag, and given a summary. Original Notam shown.

DARK NOTAMS



6 further Notams are active for NZAA. See NOTAM package for full Notam.

NZAA Increased bird activity - runway 23L approach - Wildlife [B1707/24-]

NZAA Newly erected crane near airport tower - Obstacle [B1766/24]

NZAA Newly erected cranes near airport tower. Obstacle [B1954/24]

NZAA Obstacle light out at NZAA Obstacle Light [J1613/24]

NZAA Fireworks display at NZAA Fireworks [N1615/24]

NZAA Unmanned aircraft operations at raceway. Aircraft activity [N1651/24]

TAG ID ORIGINAL NOTAM SUMMARY

AIRPORT

Closed Restriction Airport closed, staff shortage Do not use as alternate

A0133/22

APT CLSD DUE TO STAFF SHORTAGE DAILY 0600-1100Z

A0233/22 APT NOT AVBL AS ALTERNATE 2200-0400Z

APPROACH

Not avail Degraded Arrival

ILS Runway 06 U/S Outer marker on test

BUNON 3D STAR restriction

A0233/22

ILS/DME RWY 06 U/S DUE TO MAINT WEEKDAYS 0800-1400Z PILOTS TO EXER CTN AS SI

A0233/22 ILS OM RWY 24 ON TEST DO NOT USE

BUNON3D CAT A/B/C/D STAR RWY24 NOT AVBL TO CAT D AIRCRAFT A0233/22

RUNWAY

Closed Length Note

RWY 06/24 closed **RWY 06 TORA reduced** Delays for RWY 06/24

A0178/23

RWY 06/24 CLOSED FOR LANDING AND TAKE OFF EXCEPT FOR SAR REF AIP SUP 010/202

A0001/23 TORA RWY 06/24 RED TO 2243M THR DISPLACED

REINSTATING RWY 06/24 TO FULL LENGTH - EXPECT DELAYS OF 20 MINUTES. REF AIP A0128/23

TAXIWAY

Closed Closed **Taxiway D1 closed** Taxiway A closed

A012/23 A013/23

TWY D1 CLOSED REF AIP SUPPLEMENT 021/2022

TWY A CLOSED ACFT SHOULD EXPECT TO BACKTRACK TO VACATE 06/24 VIA TWY D1

ATC

Hours Radio

Tower closed at night Approach frequency problem

A021/22 A029/23 ATC SER NOT AVBL DURING NIGHT HOURS (2300-0500 UTC) DUE TO STAFF SHORTAGE AI

APP CNTL FREQ 121.4 ON BACKUP ALTN FREQ 119.7 IF ANY COMMS ISSUES

DARK NOTAMS



6 further Notams are active for VHHH. See NOTAM package for full Notam.

VHHH Increased bird activity - runway 23L approach - Wildlife [B1707/24-]

VHHH Newly erected crane near airport tower - Obstacle [B1766/24]

VHHH Newly erected cranes near airport tower. Obstacle [B1954/24]

VHHH Obstacle light out at airport Obstacle Light [J1613/24]

VHHH Fireworks display at airport **Fireworks** [N1615/24]

VHHH Unmanned aircraft operations at raceway. Aircraft activity [N1651/24]

TAG

SUMMARY ID FULL NOTAM

AIRPORT

Closed Restriction Airport closed, staff shortage

Do not use as alternate

A0133/22

APT CLSD DUE TO STAFF SHORTAGE DAILY 0600-1100Z

A0233/22 APT NOT AVBL AS ALTERNATE 2200-0400Z

APPROACH

Not avail Degraded Arrival ILS Runway 06 U/S
Outer marker on test
BUNON 3D STAR restriction

A0233/22

ILS/DME RWY 06 U/S DUE TO MAINT WEEKDAYS 0800-1400Z PILOTS TO EXER CTN AS SI

A0233/22 ILS OM RWY 24 ON TEST DO NOT USE

A0233/22

2 BUNON3D CAT A/B/C/D STAR RWY24 NOT AVBL TO CAT D AIRCRAFT

RUNWAY

Closed Length Note RWY 06/24 closed RWY 06 TORA reduced Delays for RWY 06/24 A0178/23 A0001/23 RWY 06/24 CLOSED FOR LANDING AND TAKE OFF EXCEPT FOR SAR REF AIP SUP 010/202

TORA RWY 06/24 RED TO 2243M THR DISPLACED

A0128/23 REINSTATING RWY 06/24 TO FULL LENGTH - EXPECT DELAYS OF 20 MINUTES. REF AIP

Now that we are looking at alternates, we send more Notams to the DARK - eg. Taxiway closures. We just give a plain english summary of each one here.

DARK NOTAMS



12 further Notams are active for NZCH. See NOTAM package for full Notam.

NZCH Taxiway A4 closed during night hours - Taxiway [B1707/24-]

NZCH Partially lit taxiway due to WIP.- Taxiway Light [B1766/24]

NZCH Newly erected cranes near airport tower. Obstacle [B1954/24]

NZCH Obstacle light out at airport Obstacle Light [J1613/24]

NZCH Fireworks display at airport Fireworks [N1615/24]

NZCH Unmanned aircraft operations at raceway. Aircraft activity [N1651/24]

NZCH Increased bird activity - runway 23L approach - Wildlife [B1707/24-]

NZCH Newly erected crane near airport tower - Obstacle [B1766/24]

NZCH Newly erected cranes near airport tower. Obstacle [B1954/24]

NZCH Obstacle light out at airport Obstacle Light [J1613/24]

NZCH Fireworks display at airport Fireworks [N1615/24]

NZCH Unmanned aircraft operations at raceway. Aircraft activity [N1651/24]

TAG

SUMMARY ID FULL NOTAM

AIRPORT

Closed Restriction Airport closed, staff shortage

Do not use as alternate

A0133/22

APT CLSD DUE TO STAFF SHORTAGE DAILY 0600-1100Z

A0233/22 APT NOT AVBL AS ALTERNATE 2200-0400Z

APPROACH

Not avail
Degraded
Arrival

ILS Runway 06 U/S
Outer marker on test
BUNON 3D STAR restriction

A0233/22

ILS/DME RWY 06 U/S DUE TO MAINT WEEKDAYS 0800-1400Z PILOTS TO EXER CTN AS SI

A0233/22 ILS OM RWY 24 ON TEST DO NOT USE

A0233/22 BUNON3D CAT A/B/C/D STAR RWY24 NOT AVBL TO CAT D AIRCRAFT

RUNWAY

Closed Length Note

RWY 06/24 closed RWY 06 TORA reduced Delays for RWY 06/24 A0178/23

RWY 06/24 CLOSED FOR LANDING AND TAKE OFF EXCEPT FOR SAR REF AIP SUP 010/202

A0001/23 TORA RWY 06/24 RED TO 2243M THR DISPLACED

A0128/23 REINSTATING RWY 06/24 TO FULL LENGTH - EXPECT DELAYS OF 20 MINUTES. REF AIP

DARK NOTAMS



3 further Notams are active for VMMC. See NOTAM package for full Notam.

VMMC Increased bird activity - runway 23L approach - Taxiway [B1707/24-]

VMMC Partially lit taxiway due to WIP.- Taxiway Light [B1766/24]

VMMC Newly erected cranes near airport tower. Obstacle [B1954/24]

AIRPORT

Closed Restriction Airport closed, staff shortage A0133/22 APT CLSD DUE TO STAFF SHORTAGE DAILY 0600-1100Z

Do not use as alternate A0233/22 APT NOT AVBL AS ALTERNATE 2200-0400Z

APPROACH

Not avail Degraded Arrival ILS Runway 06 U/S A0233/22 ILS/DME RWY 06 U/S DUE TO MAINT WEEKDAYS 0800-1400Z PILOTS TO EXER CTN AS SI

A0233/22 ILS OM RWY 24 ON TEST DO NOT USE

BUNON 3D STAR restriction A0233/22 BUNON3D CAT A/B/C/D STAR RWY24 NOT AVBL TO CAT D AIRCRAFT

RUNWAY

Closed Length Note RWY 06/24 closed A0178/23 RWY 06/24 CLOSED FOR LANDING AND TAKE OFF EXCEPT FOR SAR REF AIP SUP 010/202

RWY 06 TORA reduced A0001/23 TORA RWY 06/24 RED TO 2243M THR DISPLACED

Delays for RWY 06/24 A0128/23 REINSTATING RWY 06/24 TO FULL LENGTH - EXPECT DELAYS OF 20 MINUTES. REF AIP

DARK NOTAMS

6 further Notams are active for YBBN. See NOTAM package for full Notam.



YBBN Taxiway B7 closed during night hours - Taxiway [B1707/24-]

YBBN Partially lit taxiway due to WIP.- Taxiway Light [B1766/24]

YBBN Newly erected cranes near airport tower. Obstacle [B1954/24]

YBBN Obstacle light out at airport Obstacle Light [J1613/24]

YBBN Fireworks display at airport Fireworks [N1615/24]

Outer marker on test

YBBN Unmanned aircraft operations at raceway. Aircraft activity [N1651/24]

AYPY Port Moresby

Enroute Alt

APPROACH

Not avail Degraded Arrival

ILS Runway 06 U/S A0233/22 ILS/DME RWY 06 U/S DUE TO MAINT WEEKDAYS 0800-1400Z PILOTS TO EXER CTN AS SI

Outer marker on test A0233/22 ILS OM RWY 24 ON TEST DO NOT USE

BUNON 3D STAR restriction A0233/22 BUNON3D CAT A/B/C/D STAR RWY24 NOT AVBL TO CAT D AIRCRAFT

RUNWAY

Closed Length Note RWY 06/24 closed A0178/23 RWY 06/24 CLOSED FOR LANDING AND TAKE OFF EXCEPT FOR SAR REF AIP SUP 010/202

RWY 06 TORA reduced A0001/23 TORA RWY 06/24 RED TO 2243M THR DISPLACED

Delays for RWY 06/24 A0128/23 REINSTATING RWY 06/24 TO FULL LENGTH - EXPECT DELAYS OF 20 MINUTES. REF AIP

DARK NOTAMS

4 further Notams are active for AYPY. See NOTAM package for full Notam.



AYPY Taxiway B7 closed during night hours - Taxiway [B1707/24-]A

AYPY Partially lit taxiway due to WIP.- Taxiway Light [B1766/24]

AYPY Newly erected cranes near airport tower. Obstacle [B1954/24]

AYPY Obstacle light out at airport Obstacle Light [J1613/24]

DARK NOTAMS

17 Notams are active for YBBB. See NOTAM package for full Notam.



YBBB Route restriction Routes Q238 and Q293 not available. D2376/24

YBBB GPS GPS RAIM Briefings unavailable due maintenance. D2376/24

YBBB Route restriction Routes T98, UA732, UL7 not available D2376/24

YBBB Flight planning Flight planning requirement updated for YBCS. K0357/24

YBBB Special Use Airspace Military flying activity in R684B airspace D1878/24

YBBB Special Use Airspace Military flying activity in restricted airspace D1879/24

YBBB Special Use Airspace Military flying in R695C from 6000FT-FL140 D1882/24

YBBB Special Use Airspace Tindal Airspace restricted for military flying D1882/24

YBBB Special Use Airspace Darwin SW Airspace restricted for military activities. D1882/24

YBBB Special Use Airspace Military flying in Tindal airspace R249A D1882/24

YBBB Special Use Airspace Military flying activity in R684B airspace D1878/24

YBBB Special Use Airspace Military flying activity in restricted airspace D1879/24

YBBB Special Use Airspace Military flying in R695C from 6000FT-FL140 D1882/24

YBBB Special Use Airspace Tindal Airspace restricted for military flying D1882/24

YBBB Special Use Airspace Darwin SW Airspace restricted for military activities. D1882/24

YBBB Special Use Airspace Tindal Airspace restricted for military flying D1882/24

YBBB Trigger Notam Amendments to airspace handbook effective 13 June. D15134/24

AYPM Port Moresby FIR

FIR Notams

DARK NOTAMS

4 Notams are active for YBBB. See NOTAM package for full Notam.



AYPY ATC Comms HF outage Port Moresby FIR C2376/24

AYPY ATC Surveillance Space-based ADS-B now operational A3234/24

AYPY Library Updated phone number for air acident investigation commission B53/23

AYPY Library AIP change, ADIZ training area removed A025/22